



**Representative for the
Land Registrar for the
Land Titles Division of
Wellington (No.61)**

ALL SET SSIB AND PB MONUMENTS WERE USED DUE TO LACK OF OVERBURDEN
AND/OR PROXIMITY OF UNDERGROUND UTILITIES IN ACCORDANCE WITH
SECTION 11 (4) OF O.REG. 525/91.

FOR BEARING COMPARISONS, A ROTATION OF 0°2'20" COUNTER-CLOCKWISE WAS APPLIED TO BEARINGS ON REGISTERED PLAN 200.

THIS PLAN OF SURVEY RELATES TO AOLS PLAN SUBMISSION FORM NUMBER 2158215

